# **District Manager's Report**

**April 26, 2018** 

# Last Month's Follow up

Trash racks have been ordered for all canals and production has commenced.

C-5 racks have been constructed and delivered to Miami for galvanizing.

The District Drainage facilities mapping continues.

Pat Owens arrived on April 20 to complete the pump station inspections.

Hurricane Debris removed from all areas except C-2 at A-canal intersection and the rear swale area at 1751 NW 118 AVE. I await the Board's instruction for P.A.I.D. staff to proceed with removal of remaining debris.

## **Pump Station**

Radiator repaired and installed at station #2. Leak detected during the end of March pump test.

## **Rainfall**

This Month = 1.6"

Previous Month total = .55"

Yearly total = 7.9"

ESTABLISHED

# Canals

This Month = 3.81'

Previous Month = 4.05'

Year to Date = 4.05'

#### **Projects**

Headwall 6H/13 reinforced with rip-rap at C-6.

Water mains exposed for surveyors in South Acres.

Routine canal bank maintenance.

# Fleet

Routine oil changes for all 3 Fleet vehicles.

All vehicles have new P.A.I.D. door logos attached.

I am hopeful the Board will approve the emergency lighting for all fleet vehicles (for public and staff safety during Storm Response) or at least consider it a budget item for the coming year. The mounted Commander's stick is a directional arrow that can be removed from quote to lower cost of each vehicle by \$375.00 (x3 = \$1125.00 total).

\$6887.22 as is or \$5753.22 sans Command stick for 3 vehicles.

# Safety

An alarm at P.A.I.D. office on 4-9-18 resulted in Plantation police response to assure security of P.A.I.D. office. Alarm was due to kitchen door being left unsecured. Staff has been retrained for proper closing procedures to avoid a repeat of incident.

There are no injuries to report at this time.

#### New

I have enclosed drainage documentation related to catch basin products for Board consideration, Engineering planning and hopefully Drainage improvements. It is my belief that use of this product would minimize catch basin debris build up.

ESTABLISHED Angel Alvarez
1982 District Manager